



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

July 1, 2014

Gerald Hascall, Plant Manager  
Sunnyside Cogeneration Associates  
One Power Plant Road  
P.O. Box 159  
Sunnyside, Utah 84539

Subject: 2013 Annual Report Review Completion, Star Point Refuse, C/007/0042, Task ID #4562

Dear Mr. Hascall:

The Division staff has completed the review of the 2013 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed July 1, 2014.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock  
Coal Program Manager

DRH/sqs  
Enclosure  
O:\007042.SWF\WG4562\Color Letterhead.doc

[Print Form](#)[Submit by Email](#)[Reset Form](#)

## Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

### GENERAL INFORMATION

Company Name	Sunnyside Cogeneration Assoc.	Mine Name	Star Point Waste Fuel
Permit Number	C/007/0042	Permit expiration Date	2018-11-14
Operator Name	Plant Manager - Gerald Hascall	Phone Number	+1 (435) 888-4476
Mailing Address	PO Box 159	Email	
City	Sunnyside		
State	Ut	Zip Code	84539

### DOGM File Location or Annual Report Location

Excess Spoil Piles

☒ Required  
☐ Not Required

Submitted quarterly to DOGM

Refuse Piles

☒ Required  
☐ Not Required

Submitted quarterly to DOGM

Impoundments

☒ Required  
☐ Not Required

Submitted quarterly to DOGM

Other:

### OPERATOR COMMENTS

All impoundments performed as designed with no discharges during 2013  
The refuse pile is being excavated as intended and in conformance with the approved design  
The Disposal area / Excess Spoil Pile is in conformance with the approved plan  
UPDES permit was renewed in 2013 and will expire in 2018

### REVIEWER COMMENTS



Met Requirements



Did Not meet Requirements

The sediment ponds were inspected in 2013 and P.E. certified on a quarterly basis. The 4th quarter 2013 sediment pond report is also the 2013 Annual Certification Report. The sediment ponds were inspected and certified by a Utah P.E. as follows: 1st quarter 2013 on March 28, 2013, 2nd quarter 2013 on June 27, 2013, 3rd quarter 2013 on September 26, 2013 and 4th quarter/annual 2013 on December 19, 2013. (KRH)

The excess spoil piles was inspected and P.E. certified as follows: 1st quarter 2013 on March 28, 2013, 2nd quarter 2013 on June 27, 2013, 3rd quarter 2013 on September 26, 2013 and 4th quarter/annual 2013 on December 19, 2013. (KRH)

The refuse pile was inspected and certified as follows: 1st quarter 2013 on March 28, 2013, 2nd quarter 2013 on June 27, 2013, 3rd quarter 2013 on September 26, 2013 and 4th quarter/annual 2013 on December 19, 2013. (KRH)

## REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Two reclaimed areas within the permit boundary that were being monitored by RAG in connection with their reclamation reporting received Phase III bond release in July 2013.  
SCA excavated 356,486 tons of refuse material from this site and transported it to the SCA Sunnyside facility.  
No material was placed in the disposal area during 2013

Reviewer Comments

The Division concurs with the permittee's acknowledgment of phase III bond release on the two reclaimed areas.

# MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
Mine Map	1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Current mining plan is in the permit	#521.100 d and e	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments ☒ Met Requirements ☐ Did Not Meet Requirements

The required maps were included with the annual report. (JCO)